

****Service Bulletin****

Black Tank Flushing System

Please distribute to all customers, production plants, warranty & quality departments.

It has been brought to our attention that the B&B Molders Atmospheric Vacuum Breaker/Check valves (B&B Part# 571 Vac Chk) has been frequently installed incorrectly, resulting in potential leakage conditions.

The 571 Vac Chk must be installed with the water flow in the proper direction and orientated in an upright position with cap on top. (See Image #1)

If the 571 Vac Chk is in an incorrect position after installation or replacement, it will not work as designed and leakage will likely occur. (Image # 2)

Plumbing lines connected in reverse, (Image # 3), will not allow water flow thru the 571 Vac Chk without causing potential damage.

Any damage due to improper installation will void any and all warranty considerations.

CORRECT




IMAGE #1

INCORRECT




IMAGE #2

INCORRECT




IMAGE #3

Please contact your B & B service representative with any questions.