



52878 Airport Parkway • P.O. Box 1806 • Elkhart, IN 46515

NOVEMBER 18, 2003

RE: AIR BUBBLES IN RUBBER ROOFING

DEAR DICOR CUSTOMER:

AIR BUBBLES CAN APPEAR UNDER AN EPDM RUBBER ROOF FOR A VARIETY OF REASONS. THESE BUBBLES DO NOT INHIBIT THE PERFORMANCE OR SEAL OF THE ROOF.

SINCERELY,

DICOR CORPORATION